

Appendix D

Site Photos



Photo 1. Collapsed residence building. (Photo by D. Boles)



Photo 2. Log structure. (Photo by D. Boles)



Photo 3. Inside shaft. (Photo by D. Boles)



Photo 4. Log fence and old plywood covering shaft. (Photo by D. Boles)



Photo 5. Office/Assay building below adit. (Photo by D. Boles)



Photo 6. Adit above building in Photo 5. Partially open. (Photo by D. Boles)



Photo 7. One of many impoundments below wasterock and other workings.
(Photo by D. Boles)



Photo 8. Unnamed tributary. Water was present throughout the drainage.
Note wasterock to the left. (Photo by D. Boles)